Temperature Conversion Chart

Melting Points of Commonly Used Elements

Conversion:

Degrees F = (°C x 9/5) + 32

Degrees C = (°F - 32) x 5/9

Useful Range of Thermocouples: -458°F to +4800°F

Chart Temperatures given in Farenheit, Celsius, Rankine, and Kelvin.